

PAVEMENT PUDDLES BETWEEN WELLINGTON AND JULIEN ROADS W5 4UA

Local residents have raised concerns over the large number of puddles along this stretch of pavement in wet weather.

The puddles are a particular problem as some of them are in the immediate vicinity of the southbound “Julien Road” E2 & E3 bus stop.

A special concern is that pensioners are disproportionately reliant on the bus service and the excessive number of pavement puddles around this bus stop poses a particular handicap for the least agile members of our community.

Also, this stretch of pavement is intensively used by the parents and children walking and scootering to and from Mount Carmel RC Primary School.

Looking south from Wellington Road Junction (P1060081)



Looking south – puddles around lamppost (P1060082)



Looking south - puddles at bus shelter (P1060083)



Looking north - puddles at bus shelter (P1060085)



Looking north – towards bus shelter (P1060084)



The puddles evaporate slowly and continue to extend across the pavement for some hours after rain has ceased falling

